INSTRUCTIONS FOR ASSEMBLING YOUR

Metal Canvas Floater

HARDWARE














6 - SCREWS 1 - HANGING WIRE

Note: Don't let things get all scratchy! Place your frame face down on a smooth, flat surface when assembling. The hardware track on the back of the frame will make a shape when facing upwards.

- With (1) B Angle on top of (1) A Angle, insert one pair into each end of the Hardware Track in the bottom Frame section.
 A and B letters should face each other.
- Slide both Frame side sections onto the exposed A and B Angles, tighten each Screw lightly.







- 3. Slide the Hangers down the Hardware Track a third of the way from the top of the Frame.
- Insert remaining A and B Angles into each end of the top Frame section. Tighten Screws lightly.
- Insert assembled top section into the Frames open Hardware Track. Lightly tighten each of the Screws in the Frame until fully tightened, to align corners.
- Place Stretched Canvas, face down, and lay fully assembled frame, face down over canvas.
- Fasten your Stretched Canvas to your Floater Frame with the enclosed Screws. Use at least one Screw per side.
- 8. Thread the Hanging Wire through each Hanger, tighten Screw to lock in place, knot, and twist remaining wire tail to secure.
- 9. Hang your masterpiece and enjoy!

